

# Service Bulletin

## Storm Limiter Reset Instructions

Form: 1604002 Rev 1



If you are not getting hot water through the hot faucet, more than likely the hot tank limiter needs to be reset. **Before attempting to reset the limiter, it is important that the hot tank switch be turned off (located behind the door on the top right side of the bottle compartment) and the unit unplugged from the electrical outlet (Fig 1).**



Turn the cooler so that you can see the rear of the unit (Fig 2). On the right top corner, there is a bright yellow sticker with a slot cut into the cabinet running top to bottom along the sticker (Fig 3). Using a flashlight or your phone, shine a light into the opening. You will see two circular controls mounted one over the other. One has a light gray cover over it with a push button in the center about the size of a pencil eraser. Using a small screw driver, gently push this button in to reset the control (Fig 4). Leave the hot tank off, but plug in the unit. Once you have water through the **HOT** faucet, turn on the hot tank switch. You should have hot water in about 15-20 minutes.



Crystal Mountain Products, Inc · 1000 H Taylor Station Rd · Gahanna OH 43230

614.454.1618 · [www.crystalcoolers.com](http://www.crystalcoolers.com)

© 2016 Crystal Mountain Products Inc.